


## **ELEMENTS FOR AUTOMATION**







**Electric motor slide** 

**Electric motor slide** 

Pneumatic slide

#### Use:

- for precise set up position of welding torch, even during welding
- set up position of torch in two axis
- moving torch in two axis
- automatic set up of torch with sensor use

### **Property:**

- module building
- one- axis or two-axis electromotor movement
- stroke 50-300 mm, others by order
- DC electromotor 90 W, 42 V
- transfer of circular movement is linear over the spindle and spherical female screw
- robust make
- minimum maintenance


# 60 60 MB

### Additional equipment:

- Control box:
  - Movement left-right, up-down. Switch on with joystick.
  - Final switches
  - Speed is linear adjustable with SCR (thyristor) regulation.

### Other control boxes by order.

- Cross shaped manual slide
- Ring for torch
- Incline element



**Cross shaped manual slide** 



Welding automation